

Test Verification of Conformity

On the basis of the tests undertaken, the samples of the below product have been found to comply with the requirements of the referenced specification at the time the tests were carried out. This verification is part of the full test report and should be read in conjunction with it.

Applicant Name &

Address:

D&D Mountain Air Cleaners dba Southwest PPE Services 309 S Paseo De Onate Espanola, NM 87532

Advanced Inspection: Advanced Cleaning:

Verified

Verified for:

Heavy Metals

Semi-volatile Organic Compounds

Biological Sanitization Effectiveness

Repair Category Tested:

Outer Shell

Thermal Liner

WL Gore Crosstech Black Type 2F Moisture Barrier w/ W.L. Gore 10880782 Repair Tape

Specification/Standard:

NFPA 1851 Standard on Selection, Care, and Maintenance of Protective Ensembles for

Structural Fire Fighting and Proximity Fire Fighting, 2020 Edition, Chapter 11

Verification Issuing Office

Name & Address:

Intertek 3933 US Route 11

Cortland, NY 13045

Date of Tests:

September 15, 2021 - May 26, 2023

Test Report Number(s):

104528773CRT-001

Verification Effective

Date:

June 13, 2023 - June 13, 2025

Signature

Name: Ann Overbaugh Position: Program Manager

ann Overbrugh

Date: 13-June-2023

This Verification is for the exclusive use of Intertek's client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this Verification. Only the Client is authorized to permit copying or distribution of this Verification. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test/inspection results referenced in this Verification are relevant only to the sample tested/inspected. This Verification by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.